


LENTZ Meio Ambiente São Paulo - SP Brazil 11-3853.2138	slug/bail test analysis HVORSLEV's method	Date: 14/06/11	Page 1
		Project: Cemitério Congonhas	
		Evaluated by: Sandro Magro	
Slug Test No. 001		Test conducted on: 13/06/11	
PM2			

350

400



Hydraulic conductivity [cm/s]: 1,09 x 10⁻³

Slug Test No. 001

Test conducted on: 13/06/11

PM2


PM2

Static water level: 1,7 cm below datum

[illegible]

140

160




Hydraulic conductivity [cm/s]: $4,23 \times 10^{-3}$

Test conducted on: 13/06/11

PM3

Static water level: 3,1 cm below datum

[illegible]



Slug Test No. 001

Test conducted on: 13/06/11

PM4


PM4

Static water level: 3,5 cm below datum

[illegible]

49

56



Hydraulic conductivity [cm/s]: $5,13 \times 10^{-3}$

Static water level: 4,9 cm below datum

[illegible]